


BANAK

NIZA








NZ-0108



BANAK

NIZA




NZ-0108

AL  x1	AR  x1
B  x1	C  x1
D  x1	E  x1
F  x8	

BANAK

NIZA


NZ-0108

<p>1</p>  <p>1/4 X 70mm x16</p>	<p>2</p>  <p>1/4 X 50mm x8</p>	<p>3</p>  <p>1/4 X 20mm x8</p>	<p>4</p>  <p>x1</p>
<p>5</p>  <p>3/16 X 7/8" x4</p>	<p>6</p>  <p>Ø4 X 50mm x2</p>	<p>7</p>  <p>x4</p>	<p>8</p>  <p>Ø4 X 20mm x6</p>
 <p>Diagram showing tools and a warning symbol. The tools include a Phillips screwdriver (marked with an 'X' in a circle), a flathead screwdriver (marked with a circle), and a hammer. A warning triangle with an exclamation mark is also present.</p>			

BANAK

NIZA

NZ-0108




BANAK


NIZA

NZ-0108


1





1°



2°



3°




BANAK

NIZA

NZ-0108

2



BANAK

NIZA

NZ-0108

4

